ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W1305, W1311, W1317, W1313, W0744, W1315, W1309, W	NA, 3rd Crs Thippasandra Rd Varthur	Opp to Souharda Public school ward NO:03
Segment No.	**Total Length (m)**	
3/C-W1305/S011957	707.48	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	47.05	77.547219	13.084838	77.547356	13.084435	WO1317	END
2	47.26	77.546894	13.084748	77.547037	13.084345	WO 1313	END
3	49.49	77.548050	13.085103	77.548196	13.084679	WO 1311	END
4	48.37	77.547755	13.085007	77.547895	13.084592	WO 1309	END
5	47.05	77.547490	13.084928	77.547627	13.084525	WO 1305	END
6	43.30	77.548217	13.084592	77.548333	13.084217	WO1319	END
7	219.86	77.546524	13.084182	77.548473	13.084719	WO750	END
8	205.10	77.546650	13.084731	77.548462	13.085262	WO744	END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of RCC drains and Culverts at Adithya Nagara, Chandrappa Layout and Surrounding areas in ward No:03 Yelahanka Satellite Town Sub Division	17500000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Others	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	RCC Drains, Covering Slab and Flagging Course	003-20-000067
Work Order No.	**Work Order Date**	**Period of Extention**
EE/YNK-D/WO/184/19-20	09/11/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/02/2020	26/02/2021	No

Contractor Details

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W1305, W1311, W1317, W1313,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL BANGALURU		0.00
Phone No.	**E-Mail ID**	
9611354208		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		krishnappa
Date of Inspection	**Remarks**	
26/02/2020		

Category	Image	Photo Remark
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	26/02/2020	27/03/2020	As proposed

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W1305, W1311, W1317, W1313,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

SE	Vijay Kumar Haridas	26/02/2020	27/03/2020	Forwarded
EE	Sudhakar Reddy	26/02/2020	27/03/2020	Forwarded
AEE	Sachin	26/02/2020	27/03/2020	Forwarded
AE	KRISHNAPPA	26/02/2020	27/03/2020	PHOTOS UPLOADED
AE	KRISHNAPPA	26/02/2020	27/03/2020	CREATED

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W1305, W1311, W1317, W1313,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106